

County of Tehama
Department of Environmental Health
633 Washington St., Rm 36
Red Bluff CA 96080
Phone # (530) 527-8020
www.co.tehama.ca.us

OFFICIAL INSPECTION REPORT



Tim Potanovic, REHS - Director

Facility Name	: TEHAMA COUNTY JUVENILE JUSTICE CENTER	Owner	: TEHAMA COUNTY JUVENILE JUSTICE CENTER
Site Address	: 1790 WALNUT ST	Owner Address	: P O BOX 99
Facility ID	: FA0000700	Inspector	: EE0000005 - Tia Branton
Record ID	: PR0000357	Inspector Phone	: (530) 527-8020
License/Permit Number	: 2903-24H-1	Program:	: 2412 - Detention Facility
Person in Charge	:		:
Inspection Date	: 7/23/2020	Total Inspection Time	: 60 min.
Inspection Number	: DA0007939	Result	: 03 - Minor Violations
Purpose of Inspection	: 102 - Routine Inspection		

An inspection of your property revealed the following violations. Please note the date for reinspection. Thank you for your cooperation.

Inspection Violations

ALL UTENCILS AND EQUIPMENT SHALL BE APPROVED, AND FUNCTIONING PROPERLY - 16 35

"Comply by Date" Not Specified

Not In Compliance

Violation Description:

All utensils and equipment shall be fully operative and in good repair. (114175) All utensils and equipment shall be approved, installed properly, and meet applicable standards. (114130, 114130.1, 114130.2, 114130.3, 114130.4, 114130.5, 114132, 114133, 114137, 114139, 114153, 114155, 114163, 114165, 114167, 114169, 114177, 114180, 114182)

Corrective Description:

Inspector Comments:

Walk in Freezer STILL working in correctly. Water should not be collecting in door window and ice stalactites should not be forming inside of unit.

ALL VENTILATION SHALL MEET REQUIREMENTS - 16 38B

"Comply by Date" Not Specified

Not In Compliance

Violation Description:

Exhaust hoods shall be provided to remove toxic gases, heat, grease, vapors and smoke and be approved by the local building department. Canopy-type hoods shall extend 6# beyond all cooking equipment. All areas shall have sufficient ventilation to facilitate proper food storage. Toilet rooms shall be vented to the outside air by a screened openable window, an air shaft, or a light-switch activated exhaust fan, consistent with local building codes. (114149, 114149.1)

Corrective Description:

Inspector Comments:

Dry storage room is having some sort of ventilation issue. Mold is developing on floor. Cause shall be found and repaired immediately.

Overall Inspection Comments

Food used at facility as well as prepackaged for Senior Program and Probation workers.

Received By:

Date

Tia Branton

Date